

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 5/6/22		District: Aurangabad
Division : Gandnagar		Length (km): 4.03 KM
Name of the Road: Repair of road from Salempur to Khutehon jailpur DeVKund		
Scheme/Programme: MR		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b> BT/CC	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
<b>Observation Remarks:-</b> BT surface & CC surface is in good Condition.		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S
<b>Observation Remarks:-</b> Hume pipe culvert is in good condition.		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
<b>Observation Remarks:-</b> Informatory & Maintenance board, km & 200 m stone & Road signage is fixed in the road.		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) S

Name of Officer:- Ramesh Paswan  
 Designature:- EE.

Ajay  
 05/06/2022  
 EO, Munger

22/5.6.22  
 (Signature)  
 E-E  
 Regional Laboratory  
 Muzaffarpur