

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 6/6/22		District: Aurangabad
Division : Sandnagar		Length (km): 2.01KM
Name of the Road: House of Baleshwar Singh To ToS		
Scheme/Programme: GTSNY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement CC	
a)	Condition of Surfacing	U
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- CC pavement has visible crack & exposed aggregates at change 0 to 100m.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S
Observation Remarks:- Hume pipe culvert & RCC culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Informatory & Maintenance board, km & 200m stone & SI Road signage is fixed in Road		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)	U
--------------------------------------	---

Name of Officer:- Ratnesh Paswan
 Designature:- EE.

25/7/22
 6-6-22
 (Signature)
 E-E

Apurva
 06/06/2022
 EO, Mungar

Regional Laboratory
 Muzaffarpur