

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 6/6/22		District: Aurangabad
Division : Daudnagar		Length (km): 1.5 KM
Name of the Road: Balikari More to Balikari		
Scheme/Programme: PMGSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT/CC	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- BT & cc surface is in good condition.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S
Observation Remarks:- Hume pipe culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Informatory, Maintenance board, km & 200 m stone & Road signage is fixed in Road.		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Ratnesh Paswan

Designature:- EE

Agg
06/06/2022
EO, Muzar

21/7/22
(Signature) 6-6-22
E.E
Regional laboratory
Muzaffarpur