

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 6/6/22		District: Murangabad
Division : Sandhara		Length (km): 3.065 km
Name of the Road: Pothu Barga Road to Itwan Singuri		
Scheme/Programme: MHGSY (Gen)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
e)	Contraction Joints provided or not (CC Pavement)	N/A
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- BT surface & flank is in good condition		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S
Observation Remarks:- Hume pipe culvert & RCC culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Informatory board, maintenance board, km & 200m stone & signage is bined in the road.		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) S

Name of Officer:- Retnesh Pawan
 Designation:- EE

22/7/22
 6-6-22
 (Signature)

Regional Laboratory
 Muzaffarpur

Ajay
 20/06/2022
 EO, Muzer