

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 5/6/22	District: Aurangabad
Division : Daudnagar	Length (km): 0.88 KM
Name of the Road: Feroz-pachrukhiya Road to Dongan	
Scheme/Programme: MHG3Y(SC)	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT/cc	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

BT surface & cc surface is in good condition.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S

Observation Remarks:-

Hume pipe culvert is in good condition.

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

Informatory & Maintenance board, km & 200m stone, Road signage is fixed in Road.

4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Ratnesh Paswan
Signature:- EE

Signature) 5-6-22

E-E
Regional Laboratory
Muzaffarpur

Agar
05/06/22
EO, Muzer