

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 5/6/22		District: Aurangabad
Division : Daudnagar		Length (km): 5.0 KM
Name of the Road: Chhat Ghat to Sonwarsha to Bhainsani road in Hospur block		
Scheme/Programme: NEW MR		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
e)	Contraction Joints provided or not (CC Pavement)	N/A
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- BT surface is in good condition.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S
Observation Remarks:- RCC culvert & Hume pipe culvert is in good condition		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Informatory board, km post & 200m stone, Road singage is fixed in the road.		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)	S
--------------------------------------	---

Name of Officer:- Ratnesh Arwan
Designature:- EE

22/5/22
(Signature)

E-E
Regional Laboratory
Muzaffarpur

Ajay
06/06/22
EO, Muzer