INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 3/6/22 District: Auranga bad		
Division: Saudnasa Length (km): 4.90KM		
Name of the Road: Aurgnya bad polna Load - Jomualson		
Scheme/Programme: New MR		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B.T	1
a)	Condition of Surfacing	2
b)	Riding Quality	S
(c)	Road Camber .	S
d) ,	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
e)	Contraction Joints provided or not (CC Pavement)	W.A
I)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
B-T' surface à în good condition		
	Cross Drainage	•
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N·A
c)	Condition of railings/slab/approach for Bridges	NA
d)	Condition of Vent Clearance	2
Observation Remarks:- H.P. culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m-stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road funiture Dulanti		
board, kin postanders m Post is fixed in the road.		
4.	Compliance History	
a)	Status of ATR's & any others	
Overall Rating : Satisfactory (S)/ Unsatisfactory (U)		

Name of Officer:- Rothes Klaswar.
Designature:- Executivo Engineer

(Signature) 5.6-22
(Signature) 5.6-22
Regional Laboratory
Muzaffar Pur