

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Andhrathani

Name of Road :- Ballir Miya Houk to TOL

A. For Road

1. Damage Location Chainage(km):- 0.00, 0.100, 0.180, 0.250, 0.400, 0.650, 0.800, 0.950

2. Damage Length :- 0.180 KM

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:- Brick Ball

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:- 218.50 m

iv. Restored Length:-

B. For Bridge

1. Damage Location Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:-

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-


C. Requirement Of New CD/ Bridges

i. Name of Road:-

ii. Location/ Chainage:-

iii. Type of CD Work/ Length required:-

————— S' —————



Signature of JE/AE/EE



Signature
(Name of Inspection)

M/100-^{Balkir} ^{Miya} ^{House} ^{of} ^{TOL} ^{notable} ^{work}
Schedule XLV-Form No. 134

FDR

R. W. D. Jangla **DIVISION**

Adhira Harhi **SUB-DIVISION**

3112

MEASUREMENT BOOK

Name to work—

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH- P.D.R.					
M/W: Back to Puja House					
To /					
Agency: Departmental Work.					
Authority: E. Ex. R.W.D.					
Jhangherpur					
Area - Anandnagar					

Measurement as per J.S.					
① Restoration of Embankment and shoulder with broken bats					
1x80.00x	3.50x	0.40=	112.00		
2x15.00x	3.50x	0.30=	31.50		
1x10.00x	3.00x	0.30=	9.00		
1x10.00x	3.00x	0.30=	9.00		
1x8.00x	3.50x	0.20=	5.60		
1x7.00x	3.50x	0.20=	4.90		
1x30.00x	3.50x	0.30=	31.50		
1x20.00x	2.50x	0.30=	15.00		
			218.50		

Continuation
 (M) 10/6/22
 C.R.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of work</u>					
① Brand Pillip					
brass belt in					
sliders, damaged					
Length including					
cost of brass					
belt					
218.50 m plymace P ①					
② 12000 = 96/100					438088
					438088 =

[illegible]

Continuation