

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection :	7.6.22	District:	Kaimur
Division :	Mukania	Length (km):	1.70
Name of the Road:	Hata Durgawati Path to Machhanhatta.		
Scheme/Programme:	MR 3054 (Block - Durgawati)		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	-
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- There are undulations in partial length. width of B.T. has been shortened due to grass grown at end and improper road lining. Flank/shoulders are also not maintained properly.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	
Observation Remarks:- 		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- KM/200m stones not maintained. Main sign board not existing.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

Designature:-

R.P. Saw
EE, RWD
Flying squad-2

(Signature)

10.6.22