INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 4.6.22 District: 1023		
Date of Inspection: 4.6.22 District: Kalmur Division: Mukamis Length (km): 2.50 canal. Name of the Road: Kudra Parsthus road to Nimia via Above - Kudo Scheme/Programme: MR - 2054		
Name of the Road: Kudra Parsthus road to Nimia via Alven - Kudo		
State State Control of Control	Programme: MR-2054 (B)	Lock- Kndra)
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	5
b)	Riding Quality	5
c)	Road Camber	2
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_
e)	Contraction Joints provided or not (CC Pavement)	_
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:-		
In shoulder, Efw is to be done upto redd level and reduited with.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	5
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks: - KM, 200 m stone are not Porport		
maei	tion Remarks: KM, 200 m stone are not plained. Main figh board refuire fro	the Parky
4.	Compliance History	
a)	Status of ATR's & any others	
Overall l	Rating : Satisfactory (S)/ Unsatisfactory (U)	2
Name of Designat	Officer:- R.P. Saw ure:- EE, RWD Flying rgna -2 (Sign	ft 5.6. 21 ature)