

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection :	7.6.22	District:	Kaimur
Division :	Mohania	Length (km):	0.70
Name of the Road:	L/119 chhatta Rangark to Road to kulhariq		
Scheme/Programme:	PMGSY (Block - Durgawati)		
Sl. No.	Parameters to be checked	Remarks (S/U)	
1.	Pavement		
a)	Condition of Surfacing	S	
b)	Riding Quality	S	
c)	Road Camber	S	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U	
e)	Contraction Joints provided or not (CC Pavement)		
f)	Compaction of flank/slope & raincuts if any	U	
Observation Remarks:- In about 150 M CC road, surface is roughened and it is not properly maintained. Flank/Shoulder not maintained. E/W level is high than B.T. is few cent.			
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	—	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
d)	Condition of Vent Clearance		
Observation Remarks:-			
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U	
Observation Remarks:- KM, 200M, Boards & other road fixture not properly maintained.			
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)	U
--------------------------------------	---

Name of Officer:-
Designature:-

R.P. Sahoo
EE, RWD
Flying Squad - 2

(Signature)  10.6.22