

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection :	8.6.22	District:	Katmon
Division :	Mechanic	Length (km):	1.0
Name of the Road:	Lottery L107 Medha to Medha village tank.		
Scheme/Programme:	PMGSY		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	✓

Observation Remarks:-

Flank/shoulder not properly maintained.
 excess is overtopped in the B.T. surface at
 edge which require removal.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-
 Designature:-

R.P. Saw
 EE, RWD
 Flying squad-2

(Signature)

10.6.22