

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 4.6.22		District: Kaimur
Division : Mechanic		Length (km): 10.45
Name of the Road: Parsathu - mukhroan Line Path.		
Scheme/Programme: MR 3054		(Block - Kudra)
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	-
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	U
<b>Observation Remarks:-</b> In Binpurva village in about 100m and at Taiya uprauni village in about 50m, pcc is badly damaged. which needs maintenance. In about 300m, near culvert flank/shoulder work is not maintained. width is short. At other few place some patches available.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	
<b>Observation Remarks:-</b> 		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
<b>Observation Remarks:-</b> km, 200m stones etc are required proper maintenance.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-  
Designation:-

R.P. Saw  
EE, RWD  
Flying squad - 2

(Signature)

4.6.22