

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 4.6.22		District: Kaimur
Division : Mohan's		Length (km): 11.00
Name of the Road: Basahi to Nafeyo via Khawethi bhathayla.		
Scheme/Programme: MR 7054		(Block - Kendra)
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	-
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- In the village chhari, in about 100m length, the road is heavily damaged. In other approx. 700m length about 10% B.T. surface is damaged. Flank & shoulder E/W is not maintained in partial length.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- 		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Not properly maintained. km, 200 m, etc need to be properly maintained.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-
Designature:-

R.P. Saw
EE, RWD
Flying signed-2

(Signature)

4.6.22