## INSPECTION REPORT FOR ROUTINE MAINTENANCE

	Inspection: 8.6.22 District: Kainy	1
Division	1: Mohanis Length (km): 3.72	
Name o	The Road: Taraitha to Piyara ghat.	
	Programme: MR 3054 Block	- Atten Rampa
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	Temarks (5/0)
a)	Condition of Surfacing	The state of the s
b)	Riding Quality	U
c)	Road Camber	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_
e)	Contraction Joints provided or not (CC Pavement)	
f)	Compaction of flank/slope & raincuts if any	
Observation Remarks		
Co	In the village portion, B.T. work to intructed over old pcc obad. which ing damaged and needs repair from proper chaestained. Grown erown or	as been
isbe	not propy chaestained from former	ank shoulds
2.	and the second s	levery
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	
Observation Remarks:-		
- 3.	Road Rurniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Deplaced		
ma	tion Remarks:- NA froberty maintained win board in which beneth is 3.20 Km.	instead of 7.22
4.	Compliance History	July District Control
a)	Status of ATR's & any others	
Overall	Rating : Satisfactory (S)/ Unsatisfactory (U)	U
Name of Designat	Officer:- R.P. Saw ture:- EE, RND flying squad-2 (Signa	Pho.6.22