

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 7/6/22		District: Aurangabad
Division : Sandnagar		Length (km): 0.63 KM
Name of the Road: Gokh Gaya path Bazar Verma Jaon Bhumiha Bazar		
Scheme/Programme: MHGSY (SE)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT / CC	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- BT & CC surface is in good surface.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S
Observation Remarks:- Hume pipe culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Informatory & Maintenance board, km & 200m stone & Road signage is fixed in Road.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

Ratnesh Pawar

Designature:-

EE

(Signature)

E-E

Regional Laboratory
Muzaffarpur

Agg
EO, Muzaffarpur