

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 3.6.22		District: Kaimur
Division : Mohanias		Length (km): 1.5
Name of the Road: Nateya path to Kharhang		
Scheme/Programme: MMGSY (SC)		(Block - Kudra)
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	-
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- Undulations in B.T. surface. End B.T. work is not fully compacted in full width properly. shoulder/flank is not maintained if required w.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	-
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Even Main sign board is not properly written with all details. start date/ end date. Painting very old etc. km/100 post incomplete.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-
Designature:-

R.P. Saw
EE., RWD
Flying squad - 2

(Signature)

3.6.22