## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 4.6.22 District: Kain 48		
Length (km): U. 75		
Rock - Russ		
Scheme	Programme:	Remarks (S/U)
Sl. No.	Parameters to be checked	Mes server and the server serv
1.	Pavement	5
a)	Condition of Surfacing	U
b)	Riding Quality	
c)	Road Camber	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	
f)	Compaction of flank/slope & raincuts if any	0
Observation Remarks:- at Curves not maintaines. B.T.		
F	Compaction of Hankstope & Families II and  Ition Remarks:  Suberelevation at Curve, not main  inflace is satisfactory.  Tank shoulder of word main tained.  Tank shoulder of word main tained.  The property main tained in C.c. Portson	Road with
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	
Observation Remarks:-		
Flank /5		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	
Observation Remarks:- Signboard not properly woithen & Paintell  KM worm stones are not maintained.		
4.	Compliance History	
a)	Status of ATR's & any others	
Overall	Rating : Satisfactory (S)/ Unsatisfactory (U)	U
Name of Designa	Officer:- R.P. Saw ture:- EE RWD Flying squar-2 (Si	KC.6. 22 ignature)