

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 7.6.22		District: Kadirpur
Division : Mohanpur		Length (km): 2.8
Name of the Road: Chainpur Hata Road to Janardanpur Brahmatola.		
Scheme/Programme: MMGRY (Gey)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- B.T. Surface is satisfactory but in the c.c. there is crack in about 300m out of 200m. Flank & shoulder e/w is also not maintained.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Not properly maintained		
4.	Compliance History	
a)	Status of ATR's & any others	
Overall Rating :		Satisfactory (S)/ Unsatisfactory (U) U

Name of Officer:-
Designature:-

R.P. Saw
EE, RWD
Flying Squad-2

(Signature) 10.6.22