


# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 7/6/22		District: Alwar
Division : Jaipur		Length (km): 0.9 KM
Name of the Road: Kailash Singh House to T82		
Scheme/Programme: MMGSY (SC)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT/CC	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
<b>Observation Remarks:-</b> BT & CC surface is in good condition		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S
<b>Observation Remarks:-</b> Hume pipe culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
<b>Observation Remarks:-</b> Informatory & maintenance board, km & 200m stone & Road signage is bined in Road.		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) S

Name of Officer:- Ratnesh Paswan  
 Designature:- EE

  
 (Signature)  
 E-E

  
 07/06/2022  
 EO, Munger.

Regional Laboratory  
 Muzaffarpur