INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date	of Inspection: Les 6.2.2.	
Divisi	of Inspection: 4-6.22 District: Kaimur ion: Muhanis Length (km): 10.65 rof the Road: MRL 0/ NH 30 Kudos to Parasthus ne/Programme: PMGsy Parameters to be checked.	
Name	of the Road: MRL 01 NH 30 Kindra 10.65	
Schen	ne/Programme: PMGsy	
SI. No	Parameters to be checked	
1.	Pavement Remarks (S/U)	
a)	Condition of Surfacing	
b)	Riding Quality	
c)	Road Camber	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	
f)	Compaction of flank/slope & raincuts if any	
Observ	ation Remarks:-	
	Flank/shoulder is not Properly maistadues	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	
Bearing In		
	Road Furniture	
a) s	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	
Observati	on Remarks:-	
	Compliance History	
a) S	tatus of ATR's & any others	
Overall Ra	Overall Rating : Satisfactory (S)/ Unsatisfactory (U)	
Name of O Designatur	fficer:- R.P. Saw	