

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 7/6/22		District: Aurangabad
Division : Daudnagar		Length (km): 1.879 KM
Name of the Road: Goh Gaya Road - Dowlapur		
Scheme/Programme: NEW MR		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
e)	Contraction Joints provided or not (CC Pavement)	N/A
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- BT surface is in good condition.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S
Observation Remarks:- Hume pipe culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Informatory & Maintenance board, km & 200m stone & Road signage is fixed in Road.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-
Designature:-

Ratnesh Paswan
EE

22/7/22
(Signature) 7-6-22
E-E

Regional laboratory
Muzaffarpur

Ajay
07/06/22
EO, Muzaffarpur