

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 3.6.22	District: Kaimur	
Division : Mohan's	Length (km): 6.90 km.	
Name of the Road: Lahurbari chaurahi ch. (00 to 6.40) with line Roads ch. 3600		
Scheme/Programme: to Myzari and 6400 to chhoti sagra. Block - Mohan's MR-2056		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	U
<b>Observation Remarks:-</b> Flank/shoulder E/W is required to maintain its level & width.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—
<b>Observation Remarks:-</b>		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
<b>Observation Remarks:-</b> Main sign board is not maintained. Paint & width reqd. km & 200m stones are not properly maintained.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-  
Designature:-

R.P. Saini  
EE, RWD  
Flying squad-2

(Signature)

3.6.22