INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 3.6.22 District: Kaimur		
Division	1: Mohania Length (km): 3.20 k.M.	1.	dex
Name of the Road: Indwas Khasra vent Road to Mericha More to Parsurampur			
Scheme/Programme: MR 3054 (oslook - Mohamie)			
Sl. No.		Remarks (S/U)	
1.	Pavement	I –	
a)	Condition of Surfacing	S	
b)	Riding Quality	2	
c)	Road Camber	2	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_	
e)	Contraction Joints provided or not (CC Pavement)	_	
f)	Compaction of flank/slope & raincuts if any	\cup	
Observation Remarks:- E/w in flank a shoulder is not properly maintenance. Machtaired, Needs e/w for its maintenance.			
machtaired. Needs E/W for its maintenance.			
20 12 5 2 3 5 2 5 2			
2.	Cross Drainage d		
a)	Condition of head walls in Hume pipe culverts including its painting	_	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-	
c)	Condition of railings/slab/approach for Bridges		
d)	Condition of Vent Clearance		
Observation Remarks:-			
3.	Road Furniture		
a) Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained			
Observation Remarks: - Mach board require packty. KM/200m			
Observation Remarks:- Mais board require bacintif. k.m/200 m Stones are not properly maintaine.			
4.	Compliance History	的数字的图像	
a)	Status of ATR's & any others		
Overall Rating : Satisfactory (S)/ Unsatisfactory (U)			
Name of Officer:- R.P. Saw Designature:- EE, RWD Flying Squad-2 (Signature)			