

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection :	8.6.22	District:	Kaimur
Division :	Mohania	Length (km):	2.75
Name of the Road:	Ramgarh chausa Path to Esari Path		
Scheme/Programme:	MR 3054		
Sl. No.	Parameters to be checked	Remarks (S/U)	
1.	Pavement		
a)	Condition of Surfacing	S	
b)	Riding Quality	S	
c)	Road Camber	S	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-	
e)	Contraction Joints provided or not (CC Pavement)	-	
f)	Compaction of flank/slope & raincuts if any	U	
Observation Remarks:- Flank/shoulder E/W is not properly maintained.			
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	-	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
d)	Condition of Vent Clearance		
Observation Remarks:-			
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U	
Observation Remarks:- K.M / 200m stones are not properly maintained.			
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)	S
--------------------------------------	---

Name of Officer:- R.P. Saw
 Designature:- EE. RWD
 Flying squad-2


 (Signature)
 10.6.22