INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of 1	nspection: 8.6.22 District: Kalmy	
Division	: Mrtones Length (km): 2 9	
Name of the Road: Baraura Canal to Aatolih		
Scheme Programme: 3054 MR		
8.10	Parameters to be checked	Remarks (S/U)
Z.H.	Pavement	
3)	Condition of Surfacing	A U
6)	Riding Quality	U
c)	Road Camber	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	
f)	Compaction of flank/slope & raincuts if any	1)
Observation Damarka		
After Canal alignment, Dh about Yr Kim, Lewish Underlahous are existing in B.T. part. In the part superelevations are not maintained.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	
Observa	ation Remarks:-	
		4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 -
. S .	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Main Jian board paint required. RM, 200M stones are not properly maintained.		
4.	Compliance History	The state of the s
a)	Status of ATR's & any others	
Overall Rating : Satisfactory (S)/ Unsatisfactory (U)		
Name o Designa	f Officer:- R.P. San sture:- EE RMD - Typing Shed-2 (Sig	10.6.22 nature)