INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 03/06/2022 District: ROHTAS	
	1: BIKRAMGUNJ Length (km): 1. 20 km	
	THE ROAD: SHIVPUR HALT (PMGSY) TO SHIVPU	
	Programme: MMGSY NEW MAINTENANCE P	
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	5
b)	Riding Quality	S
c)	Road Camber	5
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_
e)	Contraction Joints provided or not (CC Pavement)	_
f)	Compaction of flank/slope & raincuts if any	S
Observa	ntion Remarks:-	
2.	Cross Drainage Condition of head walls in Hume nine culverts including its painting	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	-
Observa	ntion Remarks:- NO PROVESSON FOR CD WO	RKS.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	ς
Observa	tion Remarks:-	
4.	Compliance History	
a)	Status of ATR's & any others	No
Overall	Rating : Satisfactory (S)/ Unsatisfactory (U)	SATISFACTO
		7
Name o	Officer: Sin Kant praved.	15/13

Designature:- EE

Wikash Kuman

AE

316[2022

(Signature)