INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 706/2022 District: ROHTAS		
Division			
	fthe Road: ARA SASARAM ROAD SUSART TO SAM	HAUTA FOLA	ROAD
	Programme: MMGSY NEW MAINTENANCE PO	clina and a	
Sl. No.	Parameters to be checked	Remarks (S/U)	
1.	Pavement		
a)	Condition of Surfacing	5	
b)	Riding Quality	5	
c)	Road Camber	S	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U	
e)	Contraction Joints provided or not (CC Pavement)	-	
f)	Compaction of flank/slope & raincuts if any	S	
	CC PORTION.		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-	
c)	Condition of railings/slab/approach for Bridges	_	
d)	Condition of Vent Clearance	5	
3. a) Observa	Road Furniture Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained attion Remarks:-	5	
	Compliance History		
4.	Compliance History Status of ATR's & any others	No	
a)	Status of ATIC S & any officis	110	
Overall	Satisfactory (S)/ Unsatisfactory (U)	UNSATISFA	TORY
Name of Officer:- Sri Kant Praised Designature:- EE Vitash Kuman 7/6/2022			
	`A €		