## **INSPECTION REPORT FOR ROUTINE MAINTENANCE**

Date of Inspection: 7/06/2027 District: ROHTAS		
Division: BIKRAMGUNJ Length (km): 1.550 km		
Name of the Road: LAXMANPUR TILAI PATH TO AURAI		
Scheme/Programme: MMGSY NEW MAINTENANCE POLICY 2018		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	5
c)	Road Camber	ζ
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	- Approximately
f)	Compaction of flank/slope & raincuts if any	S
Observa	ation Remarks:-	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	_
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	-
Observa	ation Remarks:-	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	NO
Overall	Satisfactory (S)/ Unsatisfactory (U)	SATESFACTORY
Name o Designa	of Officer:- Sñ Kant Prased.  Hore:- EE  Wash Gernar  1/6/2022	116/2022 nature)