## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 5 06 2022 District: ROHTAS	
Division: BIKRAMGUNJ Length (km): 1.650 Km		
Name of the Road: DINARA BIKRAMGUNJ ROAD TO NADAON		
Scheme/Programme: MMGSY NEW MAINTENANCE POLICY 2018		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	5
b)	Riding Quality	5
c)	Road Camber	5
d)	Whether free from defects such as visible cracks, expose aggregates in case of CC Pavement.	d
e)	Contraction Joints provided or not (CC Pavement)	
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	5
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	_
c)	Condition of railings/slab/approach for Bridges	_
d)	Condition of Vent Clearance	5
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	5
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	NO
Overall	Rating : Satisfactory (S)/ Unsatisfactory (U)	SATISFACTORY
Name of Designat	Officer:- Sin Kant pravid ure:- EE (Signat	J16/2022

Vikash Kumar 5/6/2027