INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 4 06 2022 District: ROHTAS		
	: BIKRAMGUNJ Length (km): 1.44 km	
Name of the Road: KOATH PWD ROAD TO JAGODHARA VIA ITWA ROAD		
	Programme: MMGSY NEW MAINTENANCE POL	ICY 2018
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	4
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	~ -
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	_
c)	Condition of railings/slab/approach for Bridges	_
d)	Condition of Vent Clearance	S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	5
Observa	ntion Remarks:-	
4.	Compliance History	
a)	Status of ATR's & any others	NO
Overall	Rating : Satisfactory (S)/ Unsatisfactory (U)	SATISFACTOR
Name o Designa	rOfficer: Sin Kard Prasol, iture: E.E. (Sig	13/2 476/2022 nature)

Vikash Kumar 4/6/2022