## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of I	nspection : 5 06/20	District: ROHTAS	
Division	: BIKRAMGUNI		n
Name of	the Road: NH 30		
Scheme/	Programme: MM9	SY NEW MAINTENANCE POL	LCA 5018
Sl. No.	P	arameters to be checked	Remarks (S/U)
1.	Pavement		
a)	Condition of Surfacing		5
b)	Riding Quality		5
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		_
e)	Contraction Joints provided or not (CC Pavement)		_
f)	Compaction of flank/slope & raincuts if any		5
	C. D.		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		5
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		5
d)	Condition of Vent Clearance		
3.	Road Furniture		
a)	Whether sign boards stones/Pavement road	S	
Observa	tion Remarks:-		
4.	Compliance History		
a)	Status of ATR's & any others		NO
Overall	Rating :		
Overall	Kathig .	Satisfactory (S)/ Unsatisfactory (U)	SATISFACTORY
		. 0	2

Name of Officer:- Sin Kant Prased.

Designature:- E.E.

Vikash Kuman

5/6/2022