

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 4/06/2022	District: ROHTAS	
Division : BIKRAMGUNJ	Length (km): 2.170 km	
Name of the Road: KOATH PIRO MAIN ROAD TO ITAWA VIA MANJHAULI		
Scheme/Programme: MMGSY NEW MAINTENANCE POLICY 2018		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	-
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- PCC PORTION CRACKED IN SOME PARTS.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- PARAPET WALL OF HP CULVERT DAMAGED.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

UNSATISFACTORY

Name of Officer:- Sd/Kant Prasad
Designature:- EE

4/6/2022
(Signature)

Vikash Kumar
4/6/2022
AE