

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 7/06/2022		District: ROHTAS
Division : BEKRAMGUNJ		Length (km): 3.250 km
Name of the Road: AMAITHI PAHAR TOLA TO MASAUNA KALI MANDER TOLA		
Scheme/Programme: MMGSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
<b>1.</b>	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks. exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
<b>2.</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:-		
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

SATISFACTORY

Name of Officer:-

Designature:-

Sri Kant Prasad,  
EE.

Sri M3  
7/6/2022  
(Signature)

Vibash Kumar  
7/6/2022  
AE