## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 4/06/2022 District: ROHTAS			
	02 14 14	igth (km): 1-630 Km	
	fthe Road: DEDMGAON TO KATA	AILBAL VIA TIL	AKPURA
Scheme	Programme: PMGSY		
Sl. No.	Parameters to be checked		Remarks (S/U)
1.	Pavement		
a)	Condition of Surfacing		5
b)	Riding Quality		5
c)	Road Camber		5
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
e)	Contraction Joints provided or not (CC Pavement)		S
f)	Compaction of flank/slope & raincuts if any		5
2.	Cross Drainage	4.50	
a)	Condition of head walls in Hume pipe cul	verts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		_
d)	Condition of Vent Clearance		5
3. a) Observa	Road Furniture  Whether sign boards/informatory/cautio stones/Pavement road markings are proviation Remarks:-		S
4.	Compliance History		
a)	Status of ATR's & any others		NO
	of Officer: Sin Kart Pranc		SATISFACTORI SATISFACTORI SATISFACTORI SATISFACTORI SATISFACTORI
	Vekash Kuman 4/6/2022	, ,	gnature)