## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 4/06/2022 District: ROHTAS	
	THE ROAD SURYAPURA 4 GRER KHURD TO SURPUR	
	Tille Hollar 30 K (1917-197) Fragi	A TASCALLA
	Parameters to be checked	Remarks (S/U)
SI. No.		,
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	
c)	Road Camber	_S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	5
f)	Compaction of flank/slope & raincuts if any	5
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	5
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	_
c)	Condition of railings/slab/approach for Bridges	_
d)	Condition of Vent Clearance	S
Josefva	tion Remarks:-	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observa	tion Remarks:-	
4.	Compliance History	
a)	Status of ATR's & any others	No
Overall	Rating : Satisfactory (S)/ Unsatisfactory (U)	SATISFACTOR
Name o	Officer: - Si kant prased.	nature) 4/6/2022
Designa	ture:- EE (Sig	nature) 4/6/2022

Vikash kumar 4/6/2022 AE