INSPECTION REPORT FOR ROUTINE MAINTENANCE

		et: Kaimur	
Division: /3Labkua Length (km): 2.350			
	the Road: Blabua Kudra road Keva	i to Sondan Baw to	4
	Programme: mosy (Gin)		
Sl. No.	Parameters to be checked		Remarks (S/U)
1.	Pavement		
a)	Condition of Surfacing		S
b)	Riding Quality		S
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S
e)	Contraction Joints provided or not (CC Pavement)		S
f)	Compaction of flank/slope & raincuts if any		S
	found satisfaction	J	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		-
d) .	Condition of Vent Clearance		S
O BSCI V	ation Remarks:- found Sahis factory		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained		S
Observ	ation Remarks:-		
	Salisfactory		
4.	Compliance History		
a)	Status of ATR's & any others		
Overal	Rating : Satisfactory (S)/ Uns	atisfactory (U)	0
Name	of Officer Vi		S
Design	ature:- T.A. RWD. Patan circle		order

तकनीकी सेलाएकीर (Signature) ग्रीभीण कार्य विभाग कार्य अंचल, पटना

B.B