

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 4/06/2022 District: KOHITAS
Division : BIKRAMGUNJ Length (km): 2.050 km
Name of the Road: BALIHAR DHUDHUNDH TO BIKRAMGUNJ TOLA CHURCH
Scheme/Programme: MMSCY

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S -
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank slope & raincuts if any	S

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	-

Observation Remarks:- NO PROVISION FOR CD WORKS.

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

SATISFACTORY

Name of Officer:-

Designation:-

Sri Kant Prasad

13/6
4/6/2022
(Signature)

Vikash Kumar
4/6/2022
AE