

INSPECTION REPORT FOR ONGOING ROADS / COMPLETE		
Name of Road: NARAR SERVICE PATH DURGADIH TO DEDHGAON DURGADIH PATH		
District: ROHTAS	Division: BIKRAMGUNJ	Block: BIKRAMGUNJ
Length of Scheme (in km): 0.320 km	Name of Scheme/Programme: MMGSY	
Status of Project:	Ongoing	
Sr. No.	Parameters to be Checked for Construction work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing under Construction	S
Description of observation :		
b)	Adequate Thickness of pavement layers constructed (Sub-base/ Base Course/ Wearing Course/ CC Pavement)	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Undulation, Poor Compaction, Poor Gradation, exposed aggregates in case of CC Pavement , Surface Cracks, Poor workmanship, etc.	-
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	S
Description of observation :		
2	Cross Drainage Structure	
Description of observation of CD works : NO PROVISION FOR CD WORKS		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

SATISFACTORY

Name of Officer:

Sri Kant Prasad.

Designation:

E.E

(Signature)

Vikash Kumar
3/6/2022
A.E