



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR MOTRABLE REPAIRING OF ROAD

F.D.R. PART - MOTRABLE RESTORATION

SAKRAILI MORE TO SAKRAILI RAI TOLA

DETAILED ESTIMATE OF F.D.R. MOTRABLE REPAIRING ROAD

ROAD LENGTH	0 TO 760	
DISTRICT	KATIHAR	
BLOCK	DANDKHORA	
DIVISION	BARSOI	
TOTAL LENGTH OF ROAD	0.760	KM
TOTAL COST OF F.D.R. PART - A	Rs. 7.025	Lacs
ADD G.S.T @ 12%	Rs. 0.843	Lacs
ADD Labour Cess @ 1%	Rs. 0.070	Lacs
ADD Seigniorage Fee @ 10%	Rs. 0.338	Lacs
TOTAL COST OF RESTORATION WORK In Rs.	Rs. 8.276	Lacs

SUBMITTED BY
The Executive Engineer,
Works Division, Barsoi

Inspection Report for Flood damage work

Date:

1. Name of PIUs- EE, RIND, Barsoi.

2. Name of Block/Road- Dand Khora, Sakrailli more to sakrailli Ray
Tola

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 154 mt

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

: bamboo pilling, Bricks bats etc.

: JCB with Labour

: 154 mt

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

Signature of JE/AE/EE

Signature

(Name of Inspector)

GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD : SAKRAILI MORE TO SAKRAILI RAI TOLA
DISTRICT KATIHAR
DIVISION BARSOI
BLOCK DANDKHORA
LENGTH OF ROAD (IN KM) 0.760

Sl. No.	ITEM OF WORK	AMOUNT (LAKHS)
1	EARTH WORK	0.000
2	HUME PIPE	0.000
3	BRICK BATS	6.199
4	SAND BAGS	0.000
5	BAMBOO WORK	0.826
6	STEEL DRUM SHEET	0.000
TOTAL COST OF PROJECT =		7.025
Add G.S.T. @ 12%		0.843
Add Labour Cess @ 1%		0.070
Add Seigniorage Fee @ 10%		0.338
Total Cost of Restoration Work =		8.276

MW
18/12/21
J.E.
RWD


J.E.
RWD


E.E.
RWD

Provisional technically Sectioned for Rs:- 8.276 (Rs:- Eight Lacs twenty Seven thousand Six hundred Only)


अधीक्षक जिला
ग्रामीण कार्य विभाग
काठमान्डौ

निरीक्षण प्रतिवेदन

अधीक्षण अभियंता, ग्रामीण कार्य विभाग, कार्य अंचल पूर्णिया के पत्रांक .1361 दिनांक 20-11-21. में दिये गये निर्देश के आलोक में दिनांक से तक ग्रामीण कार्य विभाग, कार्य अंचल पूर्णिया अन्तर्गत ग्रामीण कार्य विभाग, कार्य प्रमंडल बारसोई में प्रमंडल प्रमुख के वर्ष 2021 की बाढ़ से निम्नलिखित क्षतिग्रस्त पथों के Temporary Restoration कार्य स्थल का निरीक्षण किया गया एवं इन कार्यों को प्राकल्पन के अनुरूप पाया गया। कार्य की वर्तमान स्थिति संतोषजनक है एवं पथ इस स्थलों पर मोटेरेबल है।

Sl. NO.	Division	ROAD NAME	Road Status	LENGTH (IN KM.)	Estimated Cost for Restoration (In Lakh)	Damage Length (in Mtr.)
1	BARSOI	BASTAUL SONAILI PWD ROAD TO MAHESHPUR VIA JHUNKI		5.030	48.831	254.700
2	BARSOI	KATIHAR -SONAILI PWD ROAD - SONAILI PWD ROAD (NAWADA) VIA GHOGHRA 2		6.008	15.026	213.700
3	BARSOI	L049 GILEBIYA MORE TO BANKA TOLA		0.630	3.100	27.100
4	BARSOI	L049 NIMA VIA HAJI TOLA		1.080	4.552	146.200
5	BARSOI	PARARIYA CHOWK TO SARMATI			3.083	80.900
6	BARSOI	SAKRAILI MORE TO SAKRAILI RAI TOLA		0.760	8.276	154.800
7	BARSOI	SHIV MANDIR CHOWK TO PATRAHA BANGALI TOLA		1.768	14.626	148.400
8	BARSOI	T03-T04 TO BELRAHI (VR54)		0.750	3.466	164.400
					100.960	

MJ
08/11/22

कनीय अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रशाखा, डंडखोरा

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, डंडखोरा

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बारसोई

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बायसी