

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 6/6/22	District: Kaimur (Bhabhua)
Division : Bhabhua	Length (km): 3.2
Name of the Road: Aukhara Sangharveer road link Shahpur to Bhaishahat (via Mughai)	
Scheme/Programme: New MR (3054)	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

Found Satisfactory

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S

Observation Remarks:-

Found Satisfactory

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

Satisfactory

4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Kumar Rakosh

Signature:- T.A. RWD Patna Circle

(Signature)

Bhabhua
6/6/22
N.C.

06.06.22
प्रमोद कार्य विभाग
कार्य अंचल, पटना

