

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 08-06-2022		District: Kaimur
Division : Bhabhua		Length (km): 5.700 Km
Name of the Road: 1055 to Karwandiya Muslim Tola		
Scheme/Programme: PMGSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- found Satisfactory		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- found Satisfactory		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Satisfactory		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Kumar Rakesh

Designature:- T.A. RWD Patna circle

8/06/22  
A.E

(Signature) सहायक सलाहकार  
ग्रामीण कार्य विभाग  
कार्य अंचल, पटना

08-06-22