

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 07.06.2022		District: Kaimur
Division : Bhabhua		Length (km): 3.160 km
Name of the Road: Bhabhua-Bhagwanpur road to orogai		
Scheme/Programme:		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- <p style="text-align: center; font-size: 1.2em;">Found Satisfactory</p>		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- <p style="text-align: center; font-size: 1.2em;">Satisfactory</p>		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- <p style="text-align: center; font-size: 1.2em;">Satisfactory</p>		
4.	Compliance History	
a)	Status of ATR's & any others	-


Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Kumar Rakesh

Designature:- T. A. RWD Patna circle


 तकनीकी सलाहकार
 (Signature) र्व विभाग
 कार्य अंचल, पटना

R Kumar
 07.06.22
 NTE