

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 08-06-2022		District: Kaimur
Division : Bhabhua		Length (km): 0.900 Km
Name of the Road: LEDRI TO HATA DURGAWATI ROAD		
Scheme/Programme: M/R-3054 New - 2018		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Sound Satisfactory		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- Sound Satisfactory		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Satisfactory		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Kumar Rakesh
Designation:- T.A. RWD Patna circle

(Signature)
व तकनीकी सहायकार
ग्रामोण कार्य विभाग
कार्य अंचल, पटना

8/06/22
R.E.