## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 08-06-2022 District: Kaimur	
Division		
Name o	of the Road: TO2 to Pipariya Rojput Tola	
Scheme	Programme: mm65Y	
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	\$
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	100
e)	Contraction Joints provided or not (CC Pavement)	( <del>) ( )</del>
f)	Compaction of flank/slope & raincuts if any	5
4	found satisfoctory	
:		
2.	Cross Drainage	0
a)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting	2
a) b)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts	
a) b) c)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges	
a) b) c) d)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts	
a) b) c) d)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance	
a) b) c) d)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  vation Remarks:-  Satisfactory	
a) b) c) d) Observ	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  Vation Remarks:-  Satisfactory	
a) b) c) d) Observ 3.	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  Vation Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m	S
a) b) c) d) Observ 3.	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  Vation Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer: - Rumar Rakesh Designature: - T. A. RIND Patna circle

(Signature) कार्य विभाग कार्य अंचल, पटना