

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 8/06/2022		District: ROHTAS
Division : BIKRAMGUNJ		Length (km): 1.28 km
Name of the Road: BIKRAMGUNJ NATWAR PWD ROAD TO KOLHA ROAD		
Scheme/Programme: M/R 3054		
Sl. No.	Parameters to be checked	Remarks (S/U)
1. Pavement		
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—
Observation Remarks:-		
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4. Compliance History		
a)	Status of ATR's & any others	NO

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) SATISFACTORY

Name of Officer:- Sri Kant Prasad
Designature:- EE

13/2
8/6/2022
(Signature)

Vikash Kumar
8/6/2022
AE