## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	f Inspection: 8/66/2022 District: ROHTAS	
	n: BIKRAMGUNJ Length (km): 1.05 Km	
	of the Road: BIKRAMGUNJ ROAD TO GOTPA RO	AD
	e/Programme: M/R 3054	D (CAL)
SI. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	2
b)	Riding Quality	<i>S</i>
c)	Road Camber	5
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<u> </u>
e)	Contraction Joints provided or not (CC Pavement)	
f)	Compaction of flank/slope & raincuts if any	5
Observ	ation Remarks:-	
	Const. During and	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance ation Remarks:-	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	ک
Observa	ation Remarks:-	
4.	Compliance History	
a)	Status of ATR's & any others	No
Overall	Satisfactory (S)/ Unsatisfactory (U)	SATISFACTORY
Name o Designa	(Si	816/2022 gnature)
	Vikash Kumar 8/6/2022	