## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Data of I	nenection: AE Ab 2024	istrict: Kaimust	auch talaum ein deur der Scherheite der Scherheite der Scherheite der Scherheite der Scherheite der Scherheite
Date of I	. 2) / 4010	ength (km): 0-650 Kv	
	the Road: TOI to Belau	s Horijan Tola.	
	Programme: mmGSY		Remarks (S/U)
Sl. No.	Parameters to be checked		Kemarks (3/0)
1.	Pavement		
a)	Condition of Surfacing		5
b)	Riding Quality		5
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S
e)	Contraction Joints provided or not (CC Pavement)		S
	Compaction of flank/slope & raincuts if any		S
(f)	ation Remarks:-	•	
2.	Cross Drainage		
	Condition of head walls in Hume pipe culverts including its painting		
a) 	Condition of Abutment & Wing walls, Slab in RCC culverts		
b)	Condition of railings/slab/approach for Bridges		_
c) d)	Condition of Vent Clearance		
	ation Remarks:-		
			,
3,	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained		S
Observ	ration Remarks:- Satisfacto	ry	
4.	Compliance History		
a) .	Status of ATR's & any others		-
Name	of Officer: Kinner Pakasi	)/ Unsatisfactory (U)	s sugar
Design	vature: T. A. RWD Patra cuza	le (Sie	म्यूनिकी सलीह

05/06/22 05/06/22

(Signature)की सलीहकार ग्रामीण कार्य विधाग कार्य अंचल, पटना