

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 08.06.2022		District: Kaimur
Division : Bhabhua		Length (km): 1.570 km
Name of the Road: Lo22 to Batuaara Rajput tola		
Scheme/Programme: MMGSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Creaks developed in BT & PCC Portions required to be sealed.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- Satisfactory		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Satisfactory		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Kumar Rakesh

Designation:- T. A. RWD Patna circle

08.06.22
 (Signature)
 ग्रामीण कार्य विभाग
 कार्य अंचल, पटना

Kumar
 8.06.22
 A.C.