## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date	of Inspection: 07.06.2022 Dis	trict: Kaimur (Bha	hloria
Bhabua Length (km): 1.645			(Dilla)
THE PROPERTY OF	e of the Road: LO30 to Katkara	. 073	
Schen	ne/Programme: MMGSY		
Sl. No	Parameters to be che	ecked	Remarks (S/U)
1.	Pavement		
a)	Condition of Surfacing		3
b)	Riding Quality		S
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S
e)	Contraction Joints provided or not (CC Pay	vement)	S
f)	Compaction of flank/slope & raincuts if an	у .	S
	10416 DOLLD		
2.	Cross Drainage		
2.	Cross Drainage		
a)	Cross Drainage Condition of head walls in Hume pipe culv	erts including its painting	
a) b)	Cross Drainage  Condition of head walls in Hume pipe culve  Condition of Abutment & Wing walls, Slab	erts including its painting in RCC culverts	
a) b) c)	Cross Drainage  Condition of head walls in Hume pipe culve Condition of Abutment & Wing walls, Slab Condition of railings/slab/approach for Brid	erts including its painting in RCC culverts	
a) b) - c) d)	Cross Drainage  Condition of head walls in Hume pipe culve  Condition of Abutment & Wing walls, Slab	erts including its painting in RCC culverts	
a) b) - c) d)	Cross Drainage  Condition of head walls in Hume pipe culve Condition of Abutment & Wing walls, Slab Condition of railings/slab/approach for Brid Condition of Vent Clearance	erts including its painting in RCC culverts	
a) b) - c) d)	Cross Drainage  Condition of head walls in Hume pipe culve Condition of Abutment & Wing walls, Slab Condition of railings/slab/approach for Brid Condition of Vent Clearance	erts including its painting in RCC culverts	
a) b) c) d) Observ	Cross Drainage  Condition of head walls in Hume pipe culve Condition of Abutment & Wing walls, Slab Condition of railings/slab/approach for Brid Condition of Vent Clearance vation Remarks:-	erts including its painting o in RCC culverts dges	S
a) b) c) d) Observ  3.	Cross Drainage  Condition of head walls in Hume pipe culve Condition of Abutment & Wing walls, Slab Condition of railings/slab/approach for Brid Condition of Vent Clearance  Vation Remarks:-  Road Furniture  Whether sign boards/informatory/cautional	erts including its painting o in RCC culverts dges  ry Board/ km & 200m d and maintained	S
a) b) c) d) Observ  3.	Cross Drainage  Condition of head walls in Hume pipe culve Condition of Abutment & Wing walls, Slab Condition of railings/slab/approach for Brid Condition of Vent Clearance  vation Remarks:-  Road Furniture  Whether sign boards/informatory/cautional stones/Pavement road markings are provided	erts including its painting o in RCC culverts dges  ry Board/ km & 200m d and maintained	S

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer: - Kymova Rakesh Designature: - T. A. RWD Patna Cincle

अध्या (Signature) मिण कार्य विभाग कार्य अंचल, पटना